

PRE-RACE INSPECTION FORM

CLUB BENDIGO DATE 14/11/22

TIME OF RACE MEETING DAY TWILIGHT NIGHT

CURRENT WEATHER CONDITIONS
 Clear Sunny Overcast Windy Raining Thunderstorms

Track Watering Irrigation System Water Truck or Cart Hand Held Hoses Rain Last 3 Hrs

Lure Equipment Check Y/N Action Required/Taken
 Check main & spare cables
 Check Trip Starts
 Check Carriage & Arm
 Operate Lure Pre Race

Starting Boxes Check Y/N Action Required/Taken
 Test Boxes at All Race Starts
 Check Air Compressor
 Check Cleanliness & Condition of Rubber Mats
 Check Condition of Synthetic Grass Mats

Infrastructure Check Y/N Action Required/Taken
 Catching Pen Gate & Flap
 Camera Lenses & Mirror
 Tractor & Track Implements
 Fences, Gates & Padding

STEWARDS - Comments Below

COMMENTS

Profile A

Profile C

Profile F


Profile J

GRV Office Use Only

DIAGNOSTIC DATA

Water Content & Penetrometer Readings

	0.5m off rail	mid track
A Water Content Penetrometer	30.1	30.6
B Water Content Penetrometer	50.8	44.1
C Water Content Penetrometer	31.1	31.1
D Water Content Penetrometer	59.8	46.2
E Water Content Penetrometer	32.1	29.7
F Water Content Penetrometer	56.0	42.9
G Water Content Penetrometer	32.1	30.6
H Water Content Penetrometer	48.7	42.4
I Water Content Penetrometer	30.1	29.7
J Water Content Penetrometer	53.6	46.5
K Water Content Penetrometer	29.7	28.7
L Water Content Penetrometer	55.1	44.6
M Water Content Penetrometer	32.1	30.6
N Water Content Penetrometer	65.2	44.3
O Water Content Penetrometer	30.2	31.6
P Water Content Penetrometer	69.4	45.6
Q Water Content Penetrometer	32.1	29.2
R Water Content Penetrometer	69.0	45.1
S Water Content Penetrometer	30.1	30.1
T Water Content Penetrometer	51.1	40.0



Signed Steward

Signed Curator

Email completed form to mytrack@grv.org.au